

	Time Stamp	Comments	Error Definition	Errors
12	2004/05/12 09:47			0
13	2004/05/12 09:47			0
14	2004/05/12 09:47			0

	Type	L #	Hits	Search Text	DBs
1	BRS	L1	2995	((laser near4 power) same monitor\$5)	USPAT
2	BRS	L2	15836	hologr\$5	USPAT
3	BRS	L3	19880 8	lens	USPAT
4	BRS	L4	35893	photodiode	USPAT
5	BRS	L5	301	1 and 2	USPAT
6	BRS	L6	267	3 and 5	USPAT
7	BRS	L7	136	4 and 6	USPAT
8	BRS	L8	2181	((laser near4 power) same monitor\$5)	US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB
9	BRS	L9	27951	hologr\$5	US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB
10	BRS	L10	37944 8	lens	US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB
11	BRS	L11	40178	photodiode	US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB

	Time Stamp	Comments	Error Definition	Errors
1	2004/05/12 09:46			0
2	2004/05/12 09:30			0
3	2004/05/12 09:30			0
4	2004/05/12 09:30			0
5	2004/05/12 09:30			0
6	2004/05/12 09:30			0
7	2004/05/12 09:30			0
8	2004/05/12 09:46			0
9	2004/05/12 09:46			0
10	2004/05/12 09:46			0
11	2004/05/12 09:47			0

	Type	L #	Hits	Search Text	DBs
12	BRS	L12	149	8 and 9	US - P GPUB ; EPO; JPO; DERW ENT; IBM TDB
13	BRS	L13	138	10 and 12	US - P GPUB ; EPO; JPO; DERW ENT; IBM TDB
14	BRS	L14	46	11 and 13	US - P GPUB ; EPO; JPO; DERW ENT; IBM TDB